

# NICHROME HEATER SOLDERING IRONS/GAS-POWERED SOLDERING IRONS


SOLDERING SYSTEM  
 LEAD-FREE TEMPERATURE-CONTROLLED SOLDERING STATIONS  
 TEMPERATURE-CONTROLLED SOLDERING STATIONS  
 TEMPERATURE-CONTROLLED SOLDERING IRONS  
 HIGH EFFICIENCY SOLDERING IRONS  
 GENERAL/SPECIAL PURPOSE SOLDERING IRONS  
 SOLDERING TESTER TIP THERMOMETER  
 SOLDER POTS  
 SURFACE MOUNT / SMT PRODUCTS  
 DESOLDERINGS  
 SOLDERING ACCESSORIES  
 SOLDERING WORK MATERIALS  
 HEATED TOOLS  
 HAND TOOLS

RoHS  
**For hobby use with dual switch.**  
**DUAL-POWER SOLDERING IRONS**  
**KYP-60/70**

High 60W power when trigger is pulled.



**KYP-70** comes with heat resistant cap for quick storage.



For other replacement tips, refer to next page.

SPECIFICATIONS		
Model	KYP-60	KYP-70
Voltage	110V, 120V, 130V, 220V, 240V AC 50/60Hz	
Power Consumption	Trigger ON 60W/Trigger OFF 30W	
Heater	Nichrome Heater	
Length	175mm	
Weight	160g	
Accessories	TQ-CAP (KYP-70), Soldering Iron Tip : RB-475B	

\*The length does not include the cord bushing. The weight does not include the cord.

### REPLACEMENT PARTS / OPTIONS


Heater <b>KYP-70H</b>	Heat Resistant Cap for KYP-70 <b>TQ-CAP</b>
Recommended Stand <b>ST-11</b>	

RoHS  
**Store quickly after soldering.**  
**PORTABLE SOLDERING IRON WITH CAP**  
**CA-30R/40R**



SPECIFICATIONS		
Model	CA-30R	CA-40R
Voltage	110V, 120V, 130V, 220V, 240V AC 50/60Hz	
Power Consumption	30W	40W
Heater	Nichrome Heater	
Length	185mm	
Weight	60g	
Accessories	Soldering Iron Tip : R-48B	

\*The length does not include the cord bushing. The weight does not include the cord.





For other replacement tips, refer to next page.



### REPLACEMENT PARTS / OPTIONS

CA-30R Heater <b>KS-30H</b>	CA-40R Heater <b>KS-40H</b>
Heat Resistant Cap <b>TQ-CAP</b>	Recommended Stand <b>ST-11</b>

RoHS  
**Length only 150mm! Weight only 9g!**  
**LOW-VOLTAGE SOLDERING IRONS**  
**MI-6-6V/MI-6-12V**



The tip and heater barrel connect to the minus pole (-) of the power supply. When using power from a cigarette-lighter socket, never let the iron come into contact with the plus pole (+) of the car's electrical circuitry, or it may short-circuit or cause serious damage.

SPECIFICATIONS		
Model	MI-6-6V	MI-6-12V
Voltage	5-6V AC / DC	11-12V AC / DC
Power Consumption	6W	
Heater	Nichrome Heater	
Length	150mm	
Weight	9g	
Accessories	Soldering Iron Tip : MI-6T-SC	

\*The length does not include the cord bushing. The weight does not include the cord.

### REPLACEMENT PARTS / OPTIONS

MI-6-6V Heater <b>MI-6H-6V</b>	MI-6-12VHeater <b>MI-6H-12V</b>
Recommended Stand <b>ST-30</b>	